

HID® FARGO® HDP®5000e

Windows Printer Driver Release Notes

Driver version: 1.4.0.57
PLT-08105, A.3
April 2026



Copyright

© 2026 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, FARGO, and HDP are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
April 2026	Release notes for version 1.4.0.57.	A.3

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® HDP®5000e Windows Printer Driver version 1.4.0.57. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

Compatible operating systems:

- Windows 10 (32-bit and 64-bit)
- Windows 11 (64-bit)
- Windows Server 2016 (64-bit)
- Windows Server 2019 (64-bit)
- Windows Server 2022 (64-bit)

1.2 New features and enhancements

- Password Protection for Secure Printer Access (FSA-1455)
- Secure Imaging feature (FSA-1244)
- Added a button to export advanced parameters (FSA-1379, ISU-17621)
- Improvements to existing features
- Warn user about the TLS certificate expiration date (FSA3-1997)
- When the TLS is disabled, the printer driver UI reports "NotValidYet" certificate status for fresh certificates (FSA3-1998)
- Fix the installer - HID Registry Runner MSI exit code -1073741819 (FSA3-2051)

1.3 Resolved issues

- Resolved an issue with Fix #544 Job Data Error (FSA-1537, ISU-18446)
- Resolved an issue with multiple printer preferences for UI fixes and improvements (FSA3-2173, FSA3-2205, FSA3-2223, FSA3-2224, FSA3-2048)
- Resolved an issue where the driver displays the wrong reorder number of 084511 for YMCKK. The part number should show 084512 for YMCKK (FSA3-1264)
- Resolved an issue where the driver does not display the open door prompt when the printer door is open (FSA3-1263)
- Resolved an issue where the driver does not display the laminator card jam prompt for a laminator card jam Error#53 (FSA3-1525)
- Resolved an issue where the Status Monitor does not display any lamination errors or warnings (FSA3-1883)

1.4 Known issues

- Driver incorrectly shows the **Define Areas** in the preview window. (FSA3-980, TTP-16046)
- The printer certificate signing request generation occasionally fails. (FSA3-1909)
- The printer preferences UI may work incorrectly when the HDP®6600 printer driver in version lower than 1.2.0.X is installed on the same machine.
- HDP5000e Status Monitor - JobID is not incrementing itself (FSA3-1154)
- HDP5000e Status Monitor - missing icons after installing HDP5000e (FSA3-1156)

Revision history

Date	Description	Revision
April 2026	Release notes for version 1.4.0.57.	A.3
August 2025	Release notes for version 1.3.0.35.	A.2
April 2025	Release notes for version 1.2.0.30.	A.1
January 2025	Initial release.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2026 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-08105, Rev. A.3

Part of ASSA ABLOY